

MITT ROMNEY GOVERNOR KERRY HEALEY

Lt. Governor ROBERT C. HAAS

SECRETARY

The Commonwealth of Massachusetts Executive Office of Public Safety Department of Five Services

P.O. Box 1025 ~ State Road

Stow, Massachusetts 01775

(978) 567~3100 Fax: (978) 567~3121



STEPHEN D. COAN STATE FIRE MARSHAL

THOMAS P. LEONARD DEPUTY STATE FIRE MARSHAL

For Immediate Release:

December 14, 2006

Capt. Gerard Mahoney, (617) 349 4944

Jennifer Mieth, (978) 567-3381

Cambridge Transformer Explosion Investigation Conclusion: Tragic Accident

Contact:

Cambridge Fire Chief Gerald R. Reardon and State Fire Marshal Stephen D. Coan said today that their joint investigation into the December 8, 2006 transformer explosion at One Broadway in Cambridge has concluded. After completing the scene examination and interviews, including the one surviving but injured NSTAR employee, the team has concluded that the transformer explosion was a tragic accident. While the investigators have ruled out any criminal act, they are not able determine if human error, procedural error or a malfunction of safety mechanisms was the specific cause.

Two NSTAR employees were working on the transformer at the time of the explosion and one was killed and one was injured. Dozens of the building's occupants were also treated at local hospitals. Smoke penetrated the stairwells making escape from the high-rise building difficult.

The cause and origin investigation was jointly conducted by investigators from the Cambridge Fire Department, the Cambridge Police Department and State Police assigned to the Office of the State Fire Marshal. Assistance was received from the Mass. Department of Telecommunications and Energy and State Police assigned to the Middlesex District Attorney's Office. The U.S. Occupational Safety and Health Administration is also investigating the incident.

Code compliance officers from the Office of the State Fire Marshal and Cambridge Fire Prevention Officers have identified the point at which the smoke entered the fresh air ductwork. They have issued an order of notice to the buildings owners to hire mechanical and life safety engineers to design and implement corrective measures before the building can be re-occupied.